



Maintenance or Improvement Project Overview

Start Date	<input type="text"/>	Area	<input type="text" value="Shower House"/>
Completion Date	<input type="text"/>	Project	<input type="text" value="Replace 3 sink counter"/>
Project Leader	<input type="text"/>	Type	<input type="text" value="Repair"/>
Volunteers	<input type="text"/>		

Materials Needed Wood for countertop. Screws to mount, paint or sealer to protect counter.

Labor Hours	<input type="text"/>	Materials Cost	<input type="text"/>
-------------	----------------------	----------------	----------------------

Project Description

Particle board was used to construct the counter. Exposure to water has caused swelling and decay to form. Replace counter and waterproof as needed.

Project Updates

Project unassigned and available.

Before Image



After Image



Please contact the camp overseer (next driveway headed west from camp road) if assistance is needed or contact a Rotary Scout Reservation board member.

Updates or inquiries regarding this project can be sent

support@thkyscoutcamprotary.com